

TECHNICAL BULLETIN TB-65

IMPORTANT INFORMATION

This type of starter can have different number of teeth:

- Remy OE unit: 9 teeth
- Bosch/Valeo unit: 10 teeth
- Mitsubishi unit: 12/13 teeth

They are interchangeable without any problem.

Please pay attention to the starter by installation to not to damage the flywheel.